

TABLE OF CONTENTS

目 录

Faults Cause Analysis and Countermeasures of Coke-Thruster Smoothing-Coal System for the First Coke Oven of Baosteel (宝钢一期焦炉推焦车平煤系统故障原因分析及其措施)	
Y. H. TANG, S. H. LIU.....	1
Thermodynamic Calculation of High Alumina Limonite during the Process of Direct Reduction (高铝褐铁矿直接还原过程中的热力学计算)	
S. J. ZHENG, X. D. HAO, Y. C. HONG, L. J. XU, Y. N. BAI.....	6
Failure Analysis of Fatigue Fracture for the Percussion Shaft of the Whole Hydraulic Taphole Machine for Baosteel (宝钢全液压开口机打击轴疲劳断裂失效分析)	
Y. H. TANG, S. H. LIU.....	12
The Effect of Ultrasonic Treatment on the Microstructure and Properties of 5356 Aluminum Alloy (超声波处理对 5356 铝合金组织和性能的影响)	
Y. W. HUANG, A. M. LI, X. S. FAN.....	23
Preparation of Active Zinc Oxide from Fluorine and Arsenic Containing Zinc Oxide Fume Dusts (含氟、砷氧化锌烟灰制备活性氧化锌)	
Z. F. ZHANG, H. Z. CAO, L. K. WU, G. Q. ZHENG.....	34
Application of Hydraulic Taphole Drill in the Large Blast Furnace (全液压式开口机在大型高炉上的应用)	
Y. H. TANG, S. H. LIU.....	43
The Technique of Repairing the Inner Cover of Bell-Shaped Cooling Rolling Furnace in Bagang (八钢冷轧罩式炉内罩返修工艺)	
L. K. HU.....	50
Effect Study of Ti on Contact Fatigue Properties of 20CrMnTiH Gear Steel (Ti 对 20CrMnTiH 齿轮钢接触疲劳性能影响研究)	
L. M. FAN, J. H. PEI.....	56
Study on Kinetics of Acid Leaching of Zinc Ferrite and Leaching of Zinc Ferrite Waste Material (铁酸锌的酸浸动力学及含铁酸锌废料浸出研究)	
B. Y. HUANG, W. B. YAN, Z. X. ZHOU.....	61
Effect of Rare Earth La₂O₃ on Properties of Laser Cladding 316 L Alloy Powder Coating (稀土 La ₂ O ₃ 对激光熔覆 316 L 合金粉末熔覆层性能的影响)	
W. FU, Q. L. DENG.....	70