

TABLE OF CONTENTS

目 录

New Harmonic Current Suppressor (新型中性线谐波电流抑制器)	
X. L. SUN, W. YANG.....	135
Research Status and Prospect of Power System Risk Assessment (电力系统风险评估研究现状及展望)	
X. ZOU, Z. WANG, L. Z. SONG.....	143
Analysis of Coil Abnormality in Failure of 10 kV Switch at 220 kV Substation (220 kV 某站 10 kV 开关拒动故障中线圈异常问题分析)	
J. PAN, J. ZHAN, J. W. XIAO, J. JIN.....	149
Research on Fault Detection Method and Device for Aerospace Power Supplies (航空电源的故障检测方法 with 装置研究)	
L. LIU.....	160
Control System Design for Automatic Impregnation Equipment Based on PLC (基于 PLC 的全自动浸渗设备控制系统设计)	
B. B. WANG, Z. YANG, L. WANG, L. PAN.....	165
Rotor Initial Position Detection of Permanent Magnet Synchronous Motor (永磁同步电机的转子初始位置检测)	
S. J. WEN, L. Q. KANG, T. W. LIANG, J. M. XIAO.....	172
Determination of Epoxy Resin in Transformer Oil by FTIR Method (红外光谱法定量分析变压器油中的环氧树脂)	
H. OUYANG, Y. Y. LI, Q. WANG.....	184
An Optimized Voltage Balancing Method for Modular Multilevel Converter (一种优化的模块化多电平换流器均压控制方法)	
Y. J. LIU, J. J. SONG, Y. X. NIU.....	189
Realization of CCM Boost PFC Converter Based on Digital Control (数字控制的 CCM Boost PFC 变换器的实现方法)	
K. YUN.....	199